



XRAL Laboratories
A Division of SGS Canada Inc.

1885 Leslie Street
Don Mills, Ontario
Canada M3B 3J4
Telephone (416) 445-5755
Fax (416) 445-4152

CERTIFICATE OF ANALYSIS

Work Order: 055831

To: **ISSI Consulting Group**
Attn: **Mary Goldade**
999 18th Street
Suite 1450
DENVER
COLORADO, U.S.A. 80202

Date : 15/07/99

Copy 1 to :

Copy 2 to :

P.O. No. :
Project No. : VB170-MDL STUDY
No. of Samples : 7 SOIL
Date Submitted : 08/07/99
Report Comprises : Cover Sheet plus
Pages 1 to 1

Results for As and Pb in soil samples without addition of As and Pb

Distribution of unused material:

Pulps: STORE
Rejects: STORE

Certified By :

Dr. Hugh de Souza, General Manager
XRAL Laboratories

ISO 9002 REGISTERED

Report Footer:

L.N.R.	= Listed not received	I.S.	= Insufficient Sample
n.a.	= Not applicable	--	= No result
*INF	= Composition of this sample makes detection impossible by this method		
M after a result denotes ppb to ppm conversion, % denotes ppm to % conversion			



XRAL Laboratories
A Division of SGS Canada Inc.

Work Order: 055831

Date: 15/07/99

FINAL

Page 1 of 1

Element.	As	Pb
Method.	XRF7	XRF7
Det.Lim.	3	2
Units.	ppm	ppm
*Std XRAL04	40	82
2615 E 48TH AVE-1	25	156
2615 E 48TH AVE-2	25	156
2615 E 48TH AVE-3	26	159
2615 E 48TH AVE-4	25	157
2615 E 48TH AVE-5	26	157
2615 E 48TH AVE-6	24	161
2615 E 48TH AVE-7	26	161
*Dup 2615 E 48TH AVE	26	161